

CYBERSECURITY ALERT

Dear SonoSite Customer,

FUJIFILM SonoSite, Inc. ("SonoSite") is aware of the recent global attack of the WannaCry ransomware worm and has diligently evaluated the potential impact on its ultrasound systems and operating software. After a thorough investigation, SonoSite has determined that its ultrasound systems are not affected by this worm.

The systems listed below are not affected by WannaCry:

SonoSite Edge II ultrasound system
SonoSite SII ultrasound system
SonoSite iViz ultrasound system
SonoSite X-Porte ultrasound system
SonoSite Edge ultrasound system
SonoSite NanoMaxx ultrasound system
SonoSite M-Turbo ultrasound system

SonoSite S Series ultrasound systems
SonoSite MicroMaxx ultrasound system
SonoSite Titan ultrasound system
SonoSite iLook ultrasound system
SonoSite 180 ultrasound system
SonoSite SonoHeart ultrasound system
FUJIFILM FC1 ultrasound system

SonoSite remains committed to the safety and security of its customers, any further questions can be directed to SonoSite technical support:

Phone (U.S. or Canada) (877) 657-8118
Phone (Outside U.S. or Canada)
(425) 951-1330, or call your local representative
Fax (425) 951-6700
E-mail ffss-service@fujifilm.com
Web SonoSite.com

Europe Service Center Main: +31 20 751 2020
English support: +44 14 6234 1151
French support: +33 1 8288 0702
German support: +49 69 8088 4030
Italian support: +39 02 9475 3655
Spanish support: +34 91 123 8451
Asia Service Center +65 6380-5589

For information regarding FUJIFILM VisualSonics products, including Vevo MD, please visit:
www.visualsonics.com.